ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX: +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33,

: +91 (0265) 2638382,

E-mail: erda@erda.org Web : http://www.erda.org

TEST REPORT

Sheet: 1 of 2

NAME AND ADDRESS OF CUSTOMER	TEST REPORT NO: LIPS/605	
	DATE : 26/02/2013	
SUNSHINE TECHNICAL INDUSTRIES &	CUSTOMER REF.	DATE
TRADING F.Z.E.	NO.:	4.4/08/10040
P. O. BOX NO. 20181,	Nil	14/02/2013
AJMAN FREE ZONE,	DATE OF SAMPLE RECEIPT	DATE OF TESTING
UNITED ARAB EMIRATES.	14/02/2013	14/02/2013 to 15/02/2013
SAMPLE DESCRIPTION	SAMPLE IDENTIFICATION	
ENCLOSURE (EMPTY)	ERDA sample code no LSWGWO0109799/02	
Containing: No live parts	Drg. No.: S-1228-13 (Rev. 00) Sr. No.: Nil	
TEST DETAILS	TEST SPECIFICATION	N

IP 65 tests

Cl. No. 9.8 of IEC 62208-2011

Enclosures: i) Photographs No.: i) 109799/02/1

ii) 109799/02/2

iii) 109799/02/3

ii) Drg. No.: S-1228-13 (Rev. 00)

Test Witnessed By: Mr. Gaurav Barthwall of

M/s. Sunshine Technical Industries & Trading F.Z.E.

Remarks: Sample **conforms** to the requirement of IP 65 tests as per the

standard.

Prepared by

Checked by

Note: 1. This report relates only to the particular sample received for testing in good condition at ERDA.

2. This report cannot be reproduced in part under any circumstances.

3. Publication of this report requires prior permission in writing from Director, ERDA

4. Only the tests asked for by the customer have been carried out.

5. In case of any dispute, Vadodara will be the exclusive jurisdiction & shall be construed as where the cause has arised.

ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX: +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33.

Fax : +91 (0265) 2638382,

E-mail ; erda@erda.org
Web : http://www.erda.org



Test Report No.: LIPS/605

Date : 26/02/2013

Sheet: 2 of 2

TEST RESULTS

<u>IP 65 Tests</u>: (<u>Protection against ingress of dust and protection against water jets as per Cl. No. 9.8 of IEC 62208-2011</u>)

1.0 IP 6X test: (Protection against ingress of dust as per Cl. No. 13.4 & 13.6 of IEC 60529-2001)

The sample was kept as in normal use inside the test chamber. The required amount of talcum powder was maintained in suspension throughout the test. The pressure inside the enclosure was maintained to 200 mm column of water below atmosphere. The test was continued for 8 hrs.

- 1.1 After the test the following observation was made.
- i) No dust was found inside the enclosure.

2.0 <u>IP X5 Test: (Protection against water jets Cl. No. 14.2.5 & 14.3 of IEC 60529-2001)</u>

The sample was kept as in normal use. The unit was subjected to a stream of water from a nozzle of 6.3 mm inner diameter from all practically possible directions at a delivery rate of 12.5 l/min. The distance between nozzle and equipment was maintained approximately 3.0 m. The test was continued for 3 minutes. Ingress of water is verified by the absorbent paper positioned to occupy the base area of each protected space. The paper should project from the surface equal to the depth of the protected space or a maximum of 30 mm.

2.1 After the test following observation was made.

i) No water was found inside the enclosure.

Prepared by

Checked by



ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX: +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33,

Fax : +91 (0265) 2638382,


E-mail: erda@erda.org
Web: http://www.erda.org






Test report no.: LIPS/605

Date: 26/02/2013



Photograph No.: 109799/02/1

ENCLOSURE



ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX: +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33,


Fax : +91 (0265) 2638382,

E-mail: erda@erda.org
Web: http://www.erda.org



Test report no.: LIPS/605

Date: 26/02/2013



Photograph No.: 109799/02/2

ENCLOSURE

()

()

ERDA Road, Makarpura Industrial Estate, Vadodara-390 010, India.

EPABX: +91 (0265) 2642942, 2642964, 2642377, 3043128 / 29 / 30 / 31 / 33,


Fax : +91 (0265) 2638382,

E-mail: erda@erda.org
Web: http://www.erda.org



Test report no.: LIPS/605

Date: 26/02/2013



Photograph No.: 109799/02/3

ENCLOSURE

 $(\)$

